

Spare parts list


Brand: Dimplex

Type: PSW 1000

Part number: 361640

| Position | Description | Part number | Serv. ind. |
|----------|---|-------------|------------|
| 1 | Plug-in rosette for sleeve 2 1/2" Note: Connection heating | 4521154201E | |
| 2 | Plug-in rosette for sleeve 1 1/2" Note: Connection immersion heater | 4521154202E | |
| 3 | Plug-in rosette for sleeve 1/2" Note: Connection temperature sensor | 4521154204E | |

Note: The filter drier must always be exchanged when soldering work is carried out in the refrigerant circuit.



Images are intended for identifying the item in the spare parts list and may differ from the actual technical design.